

## 2014 Mooring work

The following is a list of the proposed mooring work to be conducted in 2014. The information for this work comes from the harbour records over the last few years.

Materials for the chain and shackle replacement are available at the club.

Any mooring that we have no information on will be inspected free, any required work will be completed and billed to member.

Relocating moorings at owner's request is \$50.

#	Mooring	Owner	Task	Completed	Cost	Remarks
1	61	S. Mason	Inspection/ relocate	2-7-14	50	Relocate at owners cost, in good condition.
2	41/64	S. King	Replace mooring lost	20-8-14	N/C	41 given to club by M. Mackay and used to replace 64 that was lost by club in 2013. New top chain fitted.
3	30	B. Mclean	Inspection	2-7-14	50	Ball in poor condition and no lines fitted.
4	10	J. Martin	Inspection	2-7-14	50	Mooring has a bad bale and should be replaced in 2015.
5	9	J. Lynn		2013	N/C	New chain fitted in 2013
6	5	R. Kelley	Inspection	2-7-14	50	Good condition new mooring lines fitted on ball.
7	67	RYC	Inspection	2-7-14	N/C	Good condition.
8	44	P. Pugsley	Inspection	2-7-14	50	Good condition
9	12	M. Wennburg	Inspection	2-7-14	50	Good condition-steel plate about 800lbs.
10	25	R. Duncan	Inspection	2-7-14	50	Good mooring
11	4	R. Ward	Inspection	2-7-14	50+	Replaced top chain.
12	34	P. Creamer		2013	N/C	Inspected 2013
13	22	B. Tennant		2013	N/C	Inspected 2013
14	40	J. Hart	Inspection	3-7-14	50+	Replaced top chain
15	38	M. Grant	Inspection	3-7-14	50	Good condition
16	52	W. Taylor	Inspection/relocate	3-7-14	50	Good condition, relocated to outer harbor.
17	20	D. Shepherd	Inspection	3-7-14	50+	Inspection chain in good condition , replaced ¾ shackle.
18	83	RYC	Inspection	3-7-14	50	Good condition (Purchased by club)
19	79	M. Edwards	Inspection	3-7-14	50+	Replaced swivel
20	39	R. Taylor	Inspection	3&30-7-14	50+	New block fitted that came off #13
21	66	A. Simpson	Inspection	3-7-14	50	Good condition
22	33	J. Zinck	Inspection relocate	3-7-14	50	Good condition, moved mooring 20' south
23	16	F. Goodfellow	Inspection relocate	3-7-14	50	Good condition, moved mooring 10' south
24	13	D. Marier	Inspection	3&30-7-14	50+	Good condition, replaced block, new ball
25	8	RYC	Inspected	25-7-14		Mooring purchased by club 13-8-14 from M. McSween
26	56	S. Brittain	Inspection	25-7-14	50	Top chain fair, inspect again in 2015
27	19	D. Mott	Relocate	25-7-14	N/C	Mooring moved out so it could be used. Look at chain in 15
28	65	D. Tait	Inspection	25-7-14	50	Good condition
29	74	D. Hennessey		2013	N/C	Inspected 2013
30	70	B. O'Neil	Inspection	25-7-14	50	Bale in poor condition, top chain fair , replace in 2015
31	72	P. Heeney	Inspection	30-7-14	50	Good condition
32	54	E. Cain	Inspection/ lost	20-8-14	N/C	Top chain failed, lost mooring see pictures
33	60	??	Inspection/ lost	20-8-14	N/C	All chain recovered, no block attached. See pictures
34	57	RYC	Inspection	20-8-14	N/C	Good mooring.
35	27	D. McPurson	Inspected/lost	15-9-14	N/C	All chain recovered, no block attached. See pictures
36	11	J. Leheup	Inspected	15-9-14	50	Good mooring in very shallow water.

### Crosby Shackles

½"	\$12.00	½"	.20/ft
5/8	\$20.00	5/8"	.35/ft
¾	\$30.00	¾"	.40/ft

¾ Swivel 20.00 (Swivels should be changed out every five years)

½" top chain \$6.00/ foot (average mooring will require about 15')

Bottom chain \$75 per length (15' average)

New blocks \$175 (2000 pounds)

Lifting mooring \$50

Complete Mooring Balls are also available at a cost of \$175.00. Price last updated 17/10/2014, may change as new supplies are purchased.

Completed 17/10/14 by Paul Creamer